



**Slinger Speedway Tech Bulletin  
March 14, 2020**

**Holley HP 650 Carburetor part#80541** - Due to the inconsistency of the booster height location in the HP 650 part#80541 Holley carburetor we will allow the boosters to be relocated to the corrected height and may be epoxied in place for safety.

KDR03142020

**Contact:** Kevin Rogers - phone: 262-749-6607 email: rogers6240@yahoo.com